

Parks- Regional Trails



Fig. 1 Creek Turnpike erosion



Fig. 2 Tisdale Trail Entrance



Fig. 3 Skelly Trail sunken asphalt



Fig. 4 Mingo Valley Trail

Parks- Interior Loop Trails



Fig. 1 Crescent Park deep cracks



Fig. 2 McClure Park ½ mi of severe fractures



Fig. 3 Centennial Park sunken asphalt



Fig. 4 Leake Park severe fractures

Parks- Parking Lots



Fig. 1 Hicks Parking Lot



Fig. 2 Manion Parking Lot



Fig. 3 Heller (West) Parking Lot



Fig. 4 Ute Parking Lot

Parks – Roofs



Fig. 1 Leaks at Reed Community Center



Fig. 2 Mohawk Shelter



Fig. 3 Carbondale Shelter



Fig. 4 Leake Shelter